



INTERIM STATEMENT

This interim statement is issued in accordance with the requirements of International Civil Aviation Organization (ICAO) Annex-13 (item 6.6) to provide an overview of the progress of safety investigation and is not meant for any legal / administrative proceedings. Therefore, contents of this interim statement are not to be used without context, and for any other purpose.

Accident/Incident Data			
1	Date and Time		21/5/2021 at 01:37 UTC
2	Classification		Serious Incident
3	Aircraft	Registration	UR-SQB
		Type	B737-800
		Manufacturer	Boeing
4	Flight	Operator	SkyUp Airlines
		Phase	Landing
		Operation Type	Commercial
5	Fatalities/Injuries		None
6	Damage To Aircraft		None
7	Accident/Incident Location		Hurghada Airport , Egypt

EGAI2021-0005

May 2023





History of the flight:

- On May 21st, 2021 Aircraft Registered UR- SQP operated by SkyUp Airline under flight no. SQP 4500 took off from Antalya Airport (LTAI). It was heading to Hurghada Airport (HEGN), There was 53 Passengers onboard with four cabin crew.
- The Air Traffic Controller cleared SQP4500 to land on runway 34R.
- At 02:07 UTC the aircraft landed on runway 34L.
- After landing, Pilot In Command (PIC) requested to vacate via taxiway V8, but Air Traffic Controller clarified that the taxiway V8 Is used for vacating runway 34L not for runway 34R, Hence After, PIC admitted his confusion.

Investigation activities conducted:

- Photographic recorded was created.
- Readouts of all available data from flight data recorder were completed.
- Interviews were conducted with Air Traffic Controller.

Recommendations already issued:

- None

Next steps:

- Completion of the Final Report

Additional comments:

- None